

RISK MANAGEMENT REPORT

TYPE Telescopic Handler

MAKE **JCB**

MODEL 531-70

CHASSIS / VIN

ENGINE NUMBER

Report Number CEA 20180416-0909

Date 16-Apr-2018

Created By Graeme Reid

Assessor Graeme Reid

Assist. Assessor(s)

Completed By Graeme Reid

Owner **CEA Brisbane**

Assessment Purpose

State QLD

TABLE OF CONTENTS

IMPORTANT INFORMATION SECTION 1

Contains information outlining the scope and any limitations applicable to this Risk Management Report

MACHINE DETAILS SECTION 2

Contains standard machine specifications and details of any extras fitted

RISK ANALYSIS, RISK EVALUATION & RISK TREATMENT SECTION 3

Contains details of the technique used to calculate risk ratings, time frame and risk treatments. Please

refer to this information when reviewing and interpreting the information in section 4 $\&\,5$

RISK TREATMENTS REQUIRED

SECTION 4 Contains detailed information regarding the risk treatments to be implemented including hazard, risk

rating, time frame, relevant standards & legislative references

RISK TREATMENTS IN PLACE

SECTION 5 Contains detailed information regarding the risk treatments in place including hazard, risk rating,

relevant standards & legislative references

IMAGES AND NOTES SECTION 6

Contains images & any relevant information entered by the assessor





SECTION 1 IMPORTANT INFORMATION

This report generated by Plant Assessor™ © Online Safety Systems on Monday, 16 Apr 2018 9:15 AM

This Risk Management Report has been prepared for -

(insert recipient name/company name)

This document has been prepared to cover the sale or transfer of this item of plant between the Company identified on the front cover and their named recipient. This report must not be used for any subsequent sale or transfer.

This document is provided to meet duty of care obligations as set out in relevant state and territory health and safety regulations for the supply of plant and the sale and transfer of plant.

The safety hazards associated with the operating and maintaining of this item of plant have been identified as far as practical by visual inspection. This item of plant is being sold in an "as-is" condition with known and unknown safety hazards. No physical testing has been conducted (eg. Wire rope tests, stress tests, structural/non-destructive tests, noise tests, vibration tests, brake tests, insulation tests etc.) unless stated otherwise in the notes.

This document is not intended to provide information on, nor warrant the mechanical, electrical or structural condition of this item of plant. Any information on standard features have been supplied through the manufacturer and should be used as a guide only until otherwise verified.

This item of plant should be further assessed, tested and inspected or dismantled as necessary to gauge any further hazards and /or risks relating to SPECIFIC WORKPLACE USE, which are currently unknown, in accordance with relevant standards, regulations and acts.

Under common law and relevant state and territory health and safety acts, regulations and codes of practice, there is a requirement for the plant owner, employer and operator to exercise a duty of care in the safe operation and maintenance of plant. Accordingly before this item of plant is supplied to, or used at any workplace it must be inspected to ensure it is in a fully operational, safe and serviceable condition and that operators and maintenance personnel are appropriately trained in the use & maintenance of this item of plant.

For further information regarding this report contact Online Safety Systems on 1300 72 88 52

SECTION 2 MACHINE DETAILS

ETAILS			Manufacturers specified noise level dBA	
			2. Ambient noise level dBA	
			3. Noise level - Operator position (high idle) dBA	
F		- NOISE TEST RESULTS	4. Noise level - Operator position (low idle) dBA	
		- NOISE TEST RESULTS	5. Noise level LHS dBA @ m (high idle)	
			6. Noise level Front dBA @ m (high idle)	
			7. Noise level RHS dBA @ m (high idle)	
HNH			8. Noise level Rear dBA @ m (high idle)	
5		ВООМ	Boom Lower (seconds)	
A			Boom Raise (seconds)	
MA	BRAKES		Brake Type	
		BUCKET	Bucket width (mm)	
		CAPACITIES	Capacity at maximum reach (kg)	
		CAFACITIES	Fuel Tank Capacity (Litres)	





	Reach with 1t load (mm)	
	Dry Weight (kg)	
	Ground clearance (mm)	
	Height (mm)	
	Length (mm)	
DIMENCIONEMEIOLITO	Lift capacity maximum height (kg)	
DIMENSIONS/WEIGHTS	Operating weight (kg)	
	Reach at maximum height (mm)	
	Turn circle diameter (mm)	
	Wheelbase (mm)	
	Width (mm)	
DRIVES	Drive	
	Engine Displacement (Ltr)	
	Engine Make & Model	
	Engine Number	
ENGINE	Number of Cylinders	
	Power (kW@rpm)	
	Power rating RPM	
	Airconditioning & heating	
EXTRAS	ROPS & FOPS	
	Stabilisers fitted?	
	Air Suspension Seat	
	Carrier Rotating Angle (degrees)	
	Chassis Type	
	Crowd (seconds)	
	Dump (seconds)	
	Extras	
	Extras B	
GENERAL	Front & Rear Brakes	
	Front, Rear & Roof Wiper & Washer	
	Heaped capacity, 2:1 SAE (m3)	
	Hydraulic Attachment Locking	
	Park Brake type	
	Tele In (seconds)	
	Tele Out (seconds)	
	Work Lights - Front	
	Work Lights Rear Hydraulic Oil Reservoir Capacity (litres)	
	Hydraulic System	
HYDRAULICS	Hydraulics - Flow Rate (I/min) / Pressure (kg/cm2)	
	Hydraulics Oil Cooler	
DI ANT OF ACCIPIOATIONS	Class	
PLANT CLASSIFICATIONS	Year	-
DETAIL	New Price	
RETAIL \$	New Price Date	
	FOPS Compliance No.	
SAFETY STRUCTURES	FOPS Serial No.	
OAI ETT STRUCTURES	ROPS Compliance No.	
	ROPS Serial No.	
STEERING	Steering Angle (degrees)	
	Steering system	
TRANSMICCION	Maximum speed (km/h)	
TRANSMISSION	Speeds F/R	
	Transmission type	
TYRES	Tyres - Front & Rear	
	Maximum lift capacity, any height (kg)	
WORK CAPABILITIES	Maximum lift height (mm)	
	Maximum reach (mm)	
	Air Conditioning	
	FOPS	
EXTRAS	Fork attachment	
	Jib attachment	
	ROPS - Cabin	





SECTION 3 RISK ANALYSIS / RISK EVALUATION

RIS	SK ANALYSIS					
4			CON:	SEQUENCE —————		-
✓ TIKELIHOOD		1. INSIGNIFICANT Dealt with by in house first aid	2. MINOR Treated by medical professionals, hospital out patients	3. MODERATE Significant non permanent injury overnight hospital stay	4. MAJOR Extensive permanent injury eg. Loss of fingers, extended hospital stay	5. CATASTROPHIC Death, permanent disabling injury eg. Loss of hand, quadriplegia
	A. Almost certain to occur in most circumstances	MEDIUM 8	HIGH 16	HIGH 18	CRITICAL 23	CRITICAL 25
	B. Likely to occur frequently	MEDIUM 7	MEDIUM 10	HIGH 17	HIGH 20	CRITICAL 24
	C. Possibly and likely to occur at sometime	LOW 3	MEDIUM 9	MEDIUM 12	HIGH 19	HIGH 22
	D. Unlikely to occur but could happen	LOW 2	LOW 5	MEDIUM 11	MEDIUM 14	HIGH 21
	E. May occur but only in rare circumstances	LOW 1	LOW 4	LOW 6	MEDIUM 13	MEDIUM 15

RISK EVALUATION	CRITICAL	Act immediately to mitigate risk. Implement risk treatment(s) in accordance with the risk treatment table below.
	HIGH	Act immediately to mitigate risk. Implement risk treatment(s) in accordance with the risk treatment table below. If the appropriate risk treatments are not immediately accessible establish interim risk treatment strategies. Permanent risk treatments must be implemented within one week.
	MEDIUM	Take reasonable steps to mitigate and monitor the risk. Implement risk treatment(s) in accordance with the risk treatment table below. Permanent risk treatments must be implemented within one month.
	LOW	Take reasonable steps to mitigate and monitor the risk. Implement risk treatment(s) in accordance with the risk treatment table below. Permanent risk treatments must be implemented within three months.

ATMENT	Selecting the most appropriate risk treatment option involves balancing the costs and efforts of implementation against the benefits derived, with regard to legal, regulatory and other requirements. (SOUTCE AS/NZS ISO 310002009)				
REAT	Eliminate	Eliminate Eliminate the risk source.			
RISKT	Substitute	Provide an alternative that is capable of performing the same task which is safer.			
	Engineering	Provide or construct a physical barrier or guard.			
	Administration	Develop policies, procedures, practices and guidelines in consultation with employees to mitigate the risk. Provide training, instruction and supervision about the risk source.			
	Personal protective	Provide personal protective equipment to protect the individual from the risk source.			





Make JCB Model 531-70

pe Telescopic Handler

Chassis / VIN Assessed By

SECTION 4 RISK TREATMENTS REQUIRED

This section of the report pertains to hazards created by use of this item of plant which currently do not have risk treatments in place. The risk treatments recommended in this section have been developed based on relevant Australian Standards, health & safety legislation, the hierarchy of risk treatment in accordance with the guidelines set forth in AS/NZS ISO 31000 – Risk Management and various other sources. The recommended risk treatment measures must be developed, implemented and validated as effective prior to the operation, maintenance or testing of this item of plant. Treatments applied must be dated and initialled adjacent the recommendations. All operators must read and understand the entire contents of this section prior to operating this item of plant.

		HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating	Time Frame	Due Date	Date Rectified	Initial
ATION	NOMINATED OPERATOR ONLY	INCORRECT OPERATION	CRITICAL 24	MEDIUM 15	Immediate	16-Apr-18		
OPERA	Only persor competent/l	tment Required: Operator Comp ns who are qualified, trained and exp icensed person available for operati item of plant.	perienced and/or hold t	the relevant certificat then only persons w	tion/license can who are supervis	operate this it	em of plant. If the etent/licensed p	nere is not a person can

SECTION 5 RISK TREATMENTS IN PLACE

References: Work Health & Safety Act & Regulations-

This section of the report pertains to risk treatments currently in place on this item of plant. This section must be read in conjunction with the safety section of the manufacturers handbook. All operators must read and understand the entire contents of this section prior to operating this item of plant. These treatments or equivalent must remain in place at all times whilst this item of plant is in operation.

	HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating			
Risk Tre	CRUSHING	HIGH 22	MEDIUM 15			
Ensure th tilt tray.	Risk Treatments in Place: SWMS Loading/Unloading Ensure that all operators follow approved SWMS/SOP when loading and unloading this machine to and from a flat top truck or trailer, low loader of tilt tray. References: Work Health & Safety Act & Regulations-					
	CRUSHING	HIGH 22	MEDIUM 15			
Ensure th	atments in Place: SWMS Load Restraint at all operators follow the approved SWMS/SOP when restraining th ces: Work Health & Safety Act & Regulations-	is machine for transport.				
Ensure th		is machine for transport. HIGH 22	MEDIUM 15			





Make JCB
Model 531-70
Type Telescopic Handler

Chassis / VIN Assessed By Date

HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating
INCORRECT OPERATION	HIGH 22	MEDIUM 15
Risk Treatments in Place: Operation Handbook The manufacturer's operation handbook has been supplied for this item of plant.		
This handbook must be available at all times to all potential operators and supervise this handbook prior to operating.	ory staff. All potential operators must	read and be familiar with
A complete risk assessment/Job Safety Analysis must be undertaken covering all o of plant. SWMS should be produced for specific tasks associated with use of this ite	perating processes and environmentement	ts associated with this item
References: Work Health & Safety Act & Regulations-		
INCORRECT OPERATION	HIGH 22	MEDIUM 15
Risk Treatments in Place: Pre-op Checklist Telescopic Handler		
A pre-operational checklist is available for this Telescopic Handler. All operators mu Handler.	st complete this checklist prior to ope	erating this Telescopic
References: Work Health & Safety Act & Regulations-		
INCORRECT OPERATION	HIGH 22	MEDIUM 15
Risk Treatments in Place: SOP Telescopic Handler Safe Operation Procedures are available for this Telescopic Handler. The informatio times whilst operating this Telescopic Handler.	on in the Safe Operation Procedures	must be followed at all
References: Work Health & Safety Act & Regulations-		
INCORRECT OPERATION	HIGH 22	MEDIUM 15
Risk Treatments in Place: Control Labels All controls including all levers, buttons, pedals, switches etc. are clearly labelled as be maintained in a clean and serviceable condition at all times. References: AS/NZS4024.1905	to their purpose and method of oper	ration. These labels must
FALLING, CRUSHING	HIGH 22	MEDIUM 15
Risk Treatments in Place: Passenger Seat Label This item of plant is fitted with a clear hazard warning label re: Operator only, No parabel must be clear and legible at all times whilst this item of plant is in operation. Legislation: State Health & Safety Legislation & Regulation	ssengers. Passengers must not be c	arried at anytime. This
References: AS1319-		
CRUSHING	HIGH 22	MEDIUM 15
Risk Treatments in Place: ROPS Label The warning label stating that the ROPS must not be damaged at any time (including legible at all times.	g cuts, drill holes and welds) must be	e present, clean and
References: AS2294, ISO3471		
CRUSHING	HIGH 22	MEDIUM 15
Risk Treatments in Place: ROPS seat belt label The advisory label stating that a "ROPS is fitted seatbelts must be worn" must be fol must be present, clean and legible at all times. Peterprese: AS2304 ISO2471	llowed at all times whilst operating th	is item of plant. This label





References: AS2294, ISO3471

Make JCB
Model 531-70
Type Telescopic Handler

Chassis / VIN Assessed By Date



Risk Treatments in Place: Electrical Approach Distances

This item of plant has a hazard warning label re: overhead electrical hazards and minimum approach distances fitted. These distances must be adhered to strictly. These labels and tables must be present, clear and legible at all times.

Spotters are required when working within 5 metres of the minimum approach distance of any live electrical apparatus.

Any encroach within the minimum approach distances must only occur if the following provisions have been met -

- 1. The machine is designed to work within the minimum approach distances
- 2. Permission has been granted by the electricity company and
- 3. Safe systems of work have been documented and approved.

References: ISO31000



COLLISION

HIGH 22

MEDIUM 15

Risk Treatments in Place: Phone Use label

This item of plant is fitted with an instruction label advising that mobile phones must not be used whilst operating this machine. Accordingly all operators must not use a mobile phone at any time whilst operating machine. If phone use is necessary then operator must place machine in park configuration in a safe position prior to phone use. Operators MUST adhere to this advice at all times.

This label must be clear and legible at all times whilst this item of plant is in operation.

References: AS1319-, ISO31000



POISONING, EXPLOSION, BURNS

HIGH 22

MEDIUM 15

Risk Treatments in Place: Tank ID Label

The tank(s) on this item of plant have clear, legible label(s) identifying their contents, and if appropriate any necessary controls re: the contents. These must be present, clear and legible at all times. (this includes radiator, hydraulic and petrol/diesel tanks)

References: Work Health & Safety Act & Regulations-



CRUSHING

HIGH 22

MEDIUM 15

Risk Treatments in Place: Hydraulic Coupler

The loader boom is fitted with an automatic hydraulic attachment coupler i.e. is remotely operated from the operator position. The coupler is fitted with a safety device which detects and displays verification that coupler locking device is engaged. After engagement operators MUST manipulate the attachment to confirm correct engagement of coupler locking device.

Once fitted the safety device must be fully functional at all times whilst this item of plant is in operation.

This device must be checked as part of your daily pre-operational checklist, if any fault is detected at any time then operation must cease until the fault is rectified.

References: ISO31000



POOR SIGNAGE

HIGH 22

HIGH 21

Risk Treatments in Place: Rated Capacity (SWL) Label

This item of plant has a rated capacity (SWL) label. This capacity must not be exceeded at any time during operation. This label must be clear and legible at all times whilst this item of plant is in operation.

References: AS1418.1



OPERATIONAL MALFUNCTION, NON COMPLIANCE

HIGH 21

MEDIUM 15

Risk Treatments in Place: Log Book

The plant log book is available for this item of plant, ensure that all service, maintenance, inspections and use are recorded in the log.


References: AS2550.19-





Make JCB

Model 531-70 Type Telescopic Handler Chassis / VIN Assessed By



Risk Treatments in Place: Articulated Joint Crush Label

This item of plant has clear hazard warning labels re: crush zone, keep clear, that are attached to each side of the articulated joint. These must be present, clear and legible at all times whilst this item of plant is in operation.

References: AS/NZS4024.1201



CRUSHING

HIGH 21

MEDIUM 15

Risk Treatments in Place: Loader Crush Zone Label

The loader boom on this item of plant is fitted with a hazard warning label re: crush zone, keep clear. This label must be present and fully functional and serviceable at all times.

References: AS1319-



HEARING LOSS

HIGH 19

MEDIUM 14

Risk Treatments in Place: Hearing Protection Label - Bystanders

The hazard warning labels re: wearing of hearing protection for bystanders attached to this item of plant refer to the level of noise produced. Permanent hearing damage will result if hearing protection is not worn. These labels must be present, clear and legible at all times whilst this item of plant is in operation.

References: AS/NZS1269, AS3781-



HEARING LOSS

HIGH 19

MEDIUM 14

Risk Treatments in Place: Hearing Protection Label - Operator

The hazard warning label(s) re: wearing of hearing protection attached to this item of plant refer to the level of noise produced. Permanent hearing damage will result if hearing protection is not worn. These labels must be present, clear and legible at all times whilst this item of plant is in operation.

References: AS/NZS1269, AS3781-



BURNS, ENTANGLEMENT, SHEARING

HIGH 19

MEDIUM 13

Risk Treatments in Place: Engine Guard Label

The engine fan and alternator belts, pulleys and gears are guarded. These guards have clear legible hazard warning labels re do not open or remove guards while engine is running. These labels must be present, legible and easily seen at all times whilst this item of plant is in operation.

References: AS1319-, AS/NZS4024.1201



FIRE

MEDIUM 13

LOW 4

Risk Treatments in Place: Fire Extinguisher

This item of plant is fitted with an approved and maintained fire extinguisher. Fire extinguisher(s) must be present and fully functional at all times. They must be readily accessible to the operator. Regular inspections must also be carried out in accordance with the manufacturer's requirements and AS 1851 – 1995

References: AS/NZS1841, AS1851



COLLISION, CRUSHING

MEDIUM 12

LOW 6

Risk Treatments in Place: Warning Device (horn)

This item of plant is fitted with a fully functional audible warning device such as a horn. This must be easily accessed by the operator, and easily identifiable by nearby pedestrians.

All operators should ensure the warning devices are functional at the start of each shift, by completing pre-start checklists. Warning devices should operate automatically where appropriate (eg reversing)

References: ISO7731





Make JCB

Type

531-70 Telescopic Handler Chassis / VIN Assessed By



This item of plant is fitted with a manufacturers load plate. This plate must be clean, free from damage and legible at all times. This load plate must contain the following information as a minimum - Manufacturers specifications re:

- 1. Plant weight.
- 2. Correct operating tyre pressures.
- 3. Lifting and angle capacity.
- 4. Maximum height to which a given load can be lifted

All operators must read, understand, use and comply with this information during operation of this item of plant.



COLLISION, STRIKING, CRUSHING

MEDIUM 12

LOW 6

Risk Treatments in Place: Tail Swing Label

The rear of this item of plant has a hazard warning label re: general plant movement, tail swing, keep clear. It must be present and fully functional and serviceable at all times.

References: AS1319-, AS/NZS4024.1201



CRUSHING

MEDIUM 9

LOW 5

Risk Treatments in Place: Stabiliser Legs

This item of plant has a hazard warning label re: crushing, adjacent the stabiliser legs. These labels must be present, clear and legible at all times.

References: AS1319-, AS/NZS4024.1201



COLLISION

MEDIUM 9

LOW 5

Risk Treatments in Place: Recovery Point Label

This item of plant is fitted with a hazard warning label adjacent the recovery tow point which states "Danger - Read manufacturer's towing instructions before towing. Failure to do so could result in DEATH or SERIOUS INJURY."

This label must be clear and legible at all times whilst this item of plant is in operation.

References: ISO31000



COLLISION, CRUSHING

CRITICAL 24

MEDIUM 15

Risk Treatments in Place: Park Brake

The park brake fitted to this item of plant is fully functional at all times. The park brake must be regularly inspected and tested. These inspections and tests must be documented as part of your plant safety programme.

References: ISO31000



CRUSHING

HIGH 22

MEDIUM 15

Risk Treatments in Place: Hydraulic Locking Devices for Stabilisers

This item of plant is fitted with hydraulic cylinder locking devices to the stabiliser legs to prevent movement in the event of hydraulic failure. These devices must be fully functional at all times whilst this item of plant is in operation.

References: AS/NZS4024.1201, AS1418.1



STRIKING, ENTANGLEMENT, COLLISION, CRUSHING

HIGH 22

MEDIUM 15

Risk Treatments in Place: Neutral Start

This item of plant has neutral start control in place. It must be fully functional and serviceable at all times whilst this item of plant is in operation.

References: AS4024.1603





JCB Model

531-70 Telescopic Handler

Chassis / VIN Assessed By Date

HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating
CRUSHING	HIGH 22	MEDIUM 15
isk Treatments in Place: Seat Belt his item of plant is fitted with an operator seat belt. This seat belt must be free fi hilst this item of plant is in operation. Operators must use this seat belt at all tim eferences: AS/NZS4024.1201	rom damage, and permanently and stunes during operation.	rdily attached at all times
INCORRECT OPERATION, CRUSHING	HIGH 22	MEDIUM 15
isk Treatments in Place: Longitudinal Stability Indicator his item of plant is fitted with a longitudinal stability indicator. This indicator warr ngitudinal stability is being approached. This warning must not be ignored. Ope ngitudinal instability. This item of plant must not be operated if this device is not eferences: AS1418.19	erators must immediately take the appro	ated capacity based on opriate actions to decreas
CRUSHING, INCORRECT OPERATION	HIGH 22	MEDIUM 15
vel and permitted lateral slope as specified by the rated capacity chart. The ma sytime during operation of this item of plant. Operation of this item of plant other lly functional. CRUSHING, INCORRECT OPERATION	ximum permissable lateral slope must	not be exceeded at
sk Treatments in Place: Longitudinal Stability Limiter is item of plant is fitted with a longitudinal stability limiter. This safety device restand. Operation of this item of plant must cease if this safety device is not present eferences: AS1418.19		f plant's longitudinal tippir
CRUSHING	HIGH 22	MEDIUM 15
isk Treatments in Place: Earthmoving ROPS Roll Over Protective Structure (ROPS) to AS 2294, ISO 3471, ISO 12117.1 or 2 ating this standard must be attached to the structure at all times. It must also came of plant is in operation, and accordingly seat belts must be worn at all times references: AS2294, ISO3471	arry a warning label re: wearing of seat	
CRUSHING	HIGH 22	LOW 2
isk Treatments in Place: Hydraulic Load Holding Devices he load carrying cylinders on this item of plant are fitted with automatic means (nit in the case of loss of power or hydraulic failure. These devices must be prese peration. eferences: AS1418.1		
COLLISION, CRUSHING	HIGH 22	MEDIUM 15
isk Treatments in Place: Reverse Movement Alarm reverse movement sensor alarm is fitted to this item of plant. It must be fully fur peration.	nctional and serviceable at all times wh	ilst this item of plant is in





References: ISO7731



CUTTING, ENTANGLEMENT, SHEARING

HIGH 22

Prelim. Risk Rating

Residual Risk Rating
MEDIUM 15

Risk Treatments in Place: Emergency Stop Device

This item of plant is fitted with an emergency stop device.

The emergency stop must meet all of the following criteria whilst this item of plant is in operation:

HAZARD(S)

- 1. Is operational
- 2. Is coloured red with yellow background
- 3. Is clearly labeled as to purpose and method of operation
- 4. Is easily accessible to the operator(s) at all times whilst operating this item of plant
- 5. Resetting of emergency stop does not automatically restart machine
- 6. Is located at each operator control station.

References: AS/NZS4024.1604



ENTANGLEMENT, SHEARING, CRUSHING, BURNS, PINCHING

HIGH 22

MEDIUM 15

Risk Treatments in Place: Safe Operator Location

This machine is designed so that the operator is isolated from all danger zones whilst at the operator position. This condition must exist at all times whilst this item of plant is in operation.

References: AS/NZS4024.1201



STRIKING, BURNS

HIGH 22

MEDIUM 15

Risk Treatments in Place: Hydraulic Hoses

This item of plant has hydraulic hoses. These hoses must be inspected each day or before each use for wear and tear. If there are visible signs of wear immediate action must be taken to control the risk arising from this wear. These inspections must be documented.

Hydraulic fluid at high pressure can penetrate the skin, never use any part of your body to check for leaks. If oil penetrates the skin seek medical advice immediately. Always use a piece of cardboard or similar to check for suspected leaks.

Hydraulic pressure can be stored and is a hazard. Before disconnection or connection of hydraulic hoses complete the following steps -

- 1. Stop engine
- 2. Keep all bystanders clear of the work area
- 3. Refer to operators manual as to methods to release pressure
- 4. Wait 5 minutes

References: AS2671, AS4024



COLLISION, POOR VISIBILITY

HIGH 22

MEDIUM 15

Risk Treatments in Place: Machine Lights

This item of plant is fitted with self contained lighting. All of these lights must be fully functional and serviceable whilst this item of plant is in operation in areas of reduced light. If any of these lights stop working the operation must cease immediately and the faulty light be repaired before operation can continue in the areas of reduced light.

References: AS/NZS4024.1201



INSTABILITY, CRUSHING

HIGH 22

MEDIUM 15

Risk Treatments in Place: Stabiliser Leg Requirements

This item of plant fitted with stabiliser legs which meet the following criteria -

- 1. Means provided to securely locate each stabiliser in the retracted position
- 2. Means is provided to indicate that the stabiliser is in the correct position horizontally to provide adequate support.

All of these criteria must be met at all times whilst this item of plant is in operation.

References: AS/NZS4024.1201






Make JCB Model 531-

531-70
Telescopic Handle

Chassis / VIN Assessed By







References: ISO31000

Make JCB Model 531-

Model 531-70 Type Telescopic Handle Chassis / VIN Assessed By



NON COMPLIANCE

Prelim. Risk Rating

Residual Risk Rating

HIGH 22

LOW 5

Risk Treatments in Place: Jib Attachment

This item of plant is fitted with a jib attachment which meets the following criteria -

HAZARD(S)

- -The capacity of attachments is at least equal to the rated capacity of the machine (unit, carrier unit?)
- -Is designed to avoid unintentional disengagement

Ensure that these criteria are met at all times whilst this item of plant is in operation.

References: AS2359



NON COMPLIANCE

HIGH 22

LOW 5

Risk Treatments in Place: Jib Attachment

The attachments fitted to this item of plant are clearly marked with the following -

- -A model number or a catalogue number of the attachment
- -Rated capacity (SWL)

These markings must be present and legible at all times while this item of plant is in operation.

References: AS2359



ENTRAPMENT

HIGH 21

MEDIUM 15

Risk Treatments in Place: Two Operator Exits

The operator cabin/work area on this item of plant has a minimum of two (2) possible exits. These must be functional and accessible at all times whenever the item of plant is manned, whether during operation or maintenance activities.

References: AS1418.1



POOR VISIBILITY

HIGH 21

MEDIUM 15

Risk Treatments in Place: Windscreen Wipers

The windscreen wipers and washers fitted to this item of plant must be fully functional at all times.

References: AS/NZS4024.1201



CRUSHING

HIGH 21

LOW 5

Risk Treatments in Place: FOPS General

This item of plant is fitted with a Level I Falling Objects Protective Structure (FOPS). This structure is designed to protect the operator from small falling objects (e.g. bricks, small concrete blocks, hand tools)

Before operating this item of plant a task based risk assessment must be conducted to determine the level of FOPS required.

Level | - withstands 1,365 joules (e.g. 20kgs @ 7m drop, 70kgs @ 2m drop)

- operations such as highway maintenance, landscaping and other construction site services

Level II - withstands 11,600 joules (e.g. 200kgs @ 6m drop, 394kgs @ 3m drop)

- operations such as site clearing, overhead demolition or forestry

This task risk assessment must be undertaken before each operation, in particular when the item of plant is moved to a new location, even if it is within the same site.

References: AS2294, ISO10262, ISO3449



INCORRECT OPERATION

HIGH 20

MEDIUM 14


Risk Treatments in Place: Intuitive Controls

The controls fitted to this item of plant are orientated so that the movement of the control is consistent with the action of the machine e.g. moving a control lever to the left results in the machine turning to the left. This design feature must be maintained at all times whilst this item of plant is in operation.

References: AS/NZS4024.1906







Risk Treatments in Place: Controls Ergonomics

All controls including all levers, buttons, pedals, switches etc, are placed near the operator work position and are easy to reach and operate during the execution of the operator's normal duties. This applies for all persons within the 95th percentile of the normal population distribution.

References: AS/NZS4024.1901



STRIKING, BURNS

HIGH 19

LOW 5

Risk Treatments in Place: Hydraulic Hose Failure Shield

This item of plant is fitted with a sturdy, permanent shield(s) between the hydraulic hoses and any body parts of the operator to provide protection during a hose or component failure. This shield(s) must be present and fully functional at all times whilst this item of plant is in operation.

References: AS2671, AS4024, ISO4413



SLIPPING, INCORRECT OPERATION

HIGH 17

LOW 6

Risk Treatments in Place: Control Levers/Pedals/Buttons

All controls including all levers, buttons, pedals, switches etc. must be kept non-slip and free from damage at all times.

References: AS/NZS4024.1901



SLIPPING

MEDIUM 12

LOW 6

Risk Treatments in Place: Operator Work Area Access/Egress

Safe access and egress to the cabin/work area(s) must be maintained at all times whilst this item of plant is in operation. It must be non slip, free from damage, located at a height so as to not cause undue body stresses and strains with three points of contact available to personnel at all times.

All personnel must -

- 1. Always face the item of plant during access and egress.
- 2. Always maintain three points of contact during access and egress.
- 3. Never carry an object(s) in his/her hand(s) during access and egress.
- Never jump off machine.

References: AS1657



SLIPPING, FALLING

MEDIUM 12

LOW 6

Risk Treatments in Place: Access/Egress Instruction Label

An instruction label is fitted adjacent access/egress areas to advise all personnel of the following -

- 1. Always face the item of plant during access and egress.
- 2. Always maintain three points of contact during access and egress.
- 3. Ensure the steps are clean.
- 4. Never jump off machine.

This label must be clear and legible at all times whilst this item of plant is in operation.

References: ISO31000



COLLISION, POOR VISIBILITY

MEDIUM 12

MEDIUM 11


Risk Treatments in Place: Operator Mirrors

The operator rear view mirrors fitted to this item of plant must be fully functional and kept clean at all times. There must always be at least one mirror on each side to provide rear vision to the operator to avoid striking bystanders and objects.

References: AS1418.1, AS/NZS4024.1201







Risk Treatments in Place: Engine Bay Access

Safe access and egress to the engine bay/work area(s) must be maintained at all times whilst this item of plant is in operation. It must be non slip, free from damage, located at a height so as to not cause undue body stresses and strains with three points of contact available to personnel at all times.

All personnel must -

- 1. Always face the item of plant during access and egress.
- 2. Always maintain three points of contact during access and egress.
- 3. Never carry an object(s) in his/her hand(s) during access and egress.
- 4. Never jump off machine.

References: AS1657



ELECTRIC SHOCK, BURNS

MEDIUM 12

LOW 6

Risk Treatments in Place: Battery Cover

All batteries fitted to this item of plant are constrained to prevent displacement & fitted with a permanent sturdy cover which allows for ventilation. The constraint and cover must be present and fully functional and serviceable at all times whilst this item of plant is in operation.

References: AS/NZS4024.1201



SLIPPING, INCORRECT OPERATION

MEDIUM 9

LOW 4

Risk Treatments in Place: Operator Floor

All work area floors are non-slip and free from damage & debris.

Floor area must remain non-slip and free from damage & debris, including rubbish, tools and other items, at all times whilst this item of plant is in use.

References: AS/NZS4024.1201



STRAINS

MEDIUM 9

LOW 1

Risk Treatments in Place: Operator Seat

The operator seat fitted to this item of plant must remain free from damage and tears, and be permanently and securely fitted at all times.

References: AS/NZS4024.1401, AS1418.1



HEAT STROKE, DEHYDRATION

MEDIUM 9

LOW 4

Risk Treatments in Place: Air Conditioning

This item of plant is fitted with an air conditioned cabin. This air conditioned cabin helps control the air quality and temperature for the operator and also provides shade from the sun. The air conditioner must be fully functional and serviceable at all times whilst this item of plant is in operation.

References: ISO31000



BURNS

MEDIUM 9

LOW 5

Risk Treatments in Place: Exhaust

The engine exhaust on this item of plant is fitted with a guard to prevent injury to any person and control the risk of initiating a fire. It must be present and fully functional and serviceable at all times whilst this item of plant is in operation.

References: AS/NZS4024.1201





Make JCB

Type

I 531-70 Telescopic Handler Chassis / VIN Assessed By Date

HAZARD(S)	Prelim. Risk Rating Residual Risk		
COLLISION, CRUSHING	CRITICAL 25	MEDIUM 15	

Risk Treatments in Place: Brakes

The brakes fitted to this item of plant must be fully functional at all times whilst this item of plant is in operation. The brakes must be regularly inspected and tested. These inspections and tests must be documented as part of your plant safety programme.

References: ISO31000



CURRENT OR PREVIOUS STRUCTURAL DAMAGE

CRITICAL 25

MEDIUM 15

Risk Treatments in Place: Structural Integrity

Regular checks for structural damage must be undertaken. Look for cracks in frames/chassis (current or repaired), bends or damage to structural components, etc.

References: ISO31000



INCORRECT OPERATION

HIGH 22

MEDIUM 15

Risk Treatments in Place: Maintenance Manual

The manufacturer's maintenance manual(s) has been supplied for this item of plant

These manual(s) must be available at all times to all users and maintenance staff of this item of plant. All users and maintenance staff must read and be familiar with these handbook(s) prior to maintaining or repairing this item of plant.

A complete risk assessment/JSEA must be undertaken covering all inspection, maintenance, servicing and transportation requirements of this piece of plant prior to use.

A full assessment of the competence of people using the book(s) must also be undertaken

References: Work Health & Safety Act & Regulations-



CRUSHING

HIGH 22

MEDIUM 15

Risk Treatments in Place: ROPS Damage

The Roll Over Protective Structure (ROPS) fitted to this item of plant must remain free from damage at all times whilst this item of plant is in operation.

References: AS2294, ISO3471



STRIKING, BURNS

HIGH 22

MEDIUM 15

Risk Treatments in Place: Hydraulic Damage

The hydraulic hoses to this item of plant are free from damage and protected against damage arising from contact with the plant structure. Ensure that hoses are free from damage and that protection is in place at all times whilst this item of plant is in operation. Inspection of the hydraulic hoses and protection system should be conducted regularly and documented as part of your plant safety programme.

References: AS2671, AS4024, ISO4413



OPERATIONAL MALFUNCTION

HIGH 22

LOW 2

Risk Treatments in Place: Major Fluid Leaks

This item of plant must remain free from leaks at all times whilst in operation (this includes engine, transmission, cooling system, air, fuel, drive line, wheel hubs, steering and hydraulics). Development of a major leak will require this item of plant to be stood-down until repaired. Minor leaks detected must be repaired within 1-14 days.

References: ISO31000



COLLISION, INSTABILITY

HIGH 22

MEDIUM 15

Risk Treatments in Place: Tyres

The tyres and wheel components must be inspected as part of a "pre start" checklist. These inspections must be documented as part of your plant safety programme.

References: ISO31000





Make JCB

Type

lel 531-70

Telescopic Handler

Chassis / VIN Assessed By

Graeme Reid 16-Apr-2018 Page 16 of 17

HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating
CRUSHING	HIGH 22	LOW 2

Risk Treatments in Place: Lift Tynes

The fork tynes fitted to this item of plant are free from structural damage including deformation. If at anytime the fork tynes do become damaged including deformation then operation must cease and a competent person carry out the necessary repairs prior to operating item of plant again.

References: AS2359



OPERATIONAL MALFUNCTION

HIGH 21

MEDIUM 15

Risk Treatments in Place: Service Records

Service and maintenance records are available for this item of plant.

These records must continue to be maintained and stored in a secure area as part of your plant safety management programme. This programme includes the undertaking of regular inspections concerning the general condition of the item of plant including (but not limited to) tyre condition, oil levels and wear and tear on critical items such as brakes and steering, etc. All OEM prescribed, scheduled and non scheduled maintenance must also be documented as part of these records and attended to within a risk management framework.

References: Work Health & Safety Act & Regulations-



POOR VISIBILITY

MEDIUM 9

LOW 4

Risk Treatments in Place: Windows & Screens

Ensure the cabin/work area safety glass windows and screens are kept clean and free from cracks and other damage at all times whilst this item of plant is in use.

References: AS/NZS4024.1201, AS1418.1

SECTION 6 IMAGES AND NOTES

IMAGES

- No Images Available -

NOTES

- No Notes Available -







RISK MANAGEMENT REPORT

TYPE	Telescopic Handler	Report Number	CEA 20180416-0909
MAKE	JCB	Date	16-Apr-2018
MODEL	531-70	Created By	Graeme Reid
CHASSIS / VIN		Assessor	Graeme Reid
ENGINE NUMBER		Assist. Assessor(s)	
		Owner	CEA Brisbane
		Assessment Purpose	
		State	QLD

PURCHASER ACKNOWLEDGEMENT

I the undersigned acknowledge that I have read and understand the risk management report described above. I also acknowledge that I have recieved a copy of this risk management report. I also acknowledge that I am authorised to sign on behalf of the purchaser.



Type

Date